

Arista Access Switch Minor Alarm Resolution SOP

Node: Arista-Access-Chennai-TN-86 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_2986

Description

Resolving minor alarm ALARM_2986 on Arista Access Switch Node ID: Arista-Access-Chennai-TN-86

Potential Root Causes

Cause	Probability
Buffer Overrun	High
Port Loopback	Medium
Software Bug	Low

Diagnostic Commands

```
show system internal buffer
show interfaces status
show mac address-table
```

Resolution Steps

Step 1: {'Step': '1. Clear Buffer Overrun', 'Description': 'Clear buffer overrun using the command "clear system internal buffer"', 'Command': 'clear system internal buffer'}

Step 2: {'Step': '2. Disable Port Loopback', 'Description': 'Disable port loopback using the command "no interface [interface_name] loopback"', 'Command': 'no interface [interface_name] loopback'}

Step 3: {'Step': '3. Upgrade Software (If Applicable)', 'Description': 'Upgrade software to latest version if software bug is suspected', 'Command': 'upgrade system software'}

Post-Check Verification

```
show system internal buffer
show interfaces status
show mac address-table
```