

Arista Access Switch Alarm SOP (ALARM_5753)

Node: Arista-Access-Chennai-TN-90 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_5753

Description

Minor alarm on Arista Access Switch (Arista-Access-Chennai-TN-90) due to unexpected event.

Potential Root Causes

Cause	Probability
Incorrect configuration of VLAN settings	Medium
Incompatible firmware version	Low
Hardware issue with the switch	High

Diagnostic Commands

```
show system internal switch-summary
show vlan
show interfaces status
show version
```

Resolution Steps

- Step 1: {'Step': '1. Check VLAN configuration', 'Action': 'Verify VLAN settings on the switch and correct if necessary', 'CLI_Command': 'show vlan'}
- Step 2: {'Step': '2. Update firmware', 'Action': 'Update the switch firmware to the latest version', 'CLI_Command': 'boot system flash:/arista-image-1.2.0.bin'}
- Step 3: {'Step': '3. Replace faulty hardware', 'Action': 'Replace the faulty switch with a new one', 'Notes': 'Perform a thorough hardware inspection before proceeding'}

Post-Check Verification

```
show system internal switch-summary
show vlan
show interfaces status
show version
```