

Arista Access Switch Alarm Resolution SOP

Node: Arista-Access-Delhi-NCR-30 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_5825

Description

This SOP outlines the steps to resolve Critical Alarm ALARM_5825 on Arista Access Switch Node ID: Arista-Access-Delhi-NCR-30.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Misconfigured Settings	Low

Diagnostic Commands

```
show system internal switch detail
show hardware detail
show version
show system internal switch fabric detail
```

Resolution Steps

- Step 1: {'Step': 'Restart the switch', 'Action': 'execute reboot command', 'CLI_Command': 'reboot'}
- Step 2: {'Step': 'Check and configure the hardware settings', 'Action': 'Verify the hardware settings and configure as necessary', 'CLI_Command': 'show hardware detail'}
- Step 3: {'Step': 'Update the software', 'Action': 'Update the switch software to the latest version', 'CLI_Command': 'no shutdown; copy bootflash:arista-2.23.4F /bootflash/arista-2.23.4F; reboot'}

Post-Check Verification

```
show system internal switch detail
show hardware detail
show version
```