

Arista Access Switch Alarm Resolution SOP - ALARM_3063

Node: Arista-Access-Kolkata-WB-110 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_3063

Description

ALARM_3063 - Warning Severity Alarm on Arista Access Switch Node ID: Arista-Access-Kolkata-WB-110

Potential Root Causes

Cause	Probability
Spanning Tree Protocol (STP) Loop Detected	High
Incorrect VLAN Configuration	Medium
Switch Fabric Congestion	Low

Diagnostic Commands

```
show spanning-tree detail
show vlan
show interfaces switchport
show fabric information
```

Resolution Steps

- Step 1: {'Step': '1. Verify STP Configuration', 'Action': "Check STP status and configuration on the switch using 'show spanning-tree detail' command", 'CLI_Command': 'show spanning-tree detail'}
- Step 2: {'Step': '2. Verify VLAN Configuration', 'Action': "Verify VLAN configuration on the switch using 'show vlan' command", 'CLI_Command': 'show vlan'}
- Step 3: {'Step': '3. Verify Switch Fabric Congestion', 'Action': "Verify switch fabric congestion using 'show fabric information' command", 'CLI_Command': 'show fabric information'}
- Step 4: {'Step': '4. Correct STP Loop', 'Action': 'Correct STP loop by removing any redundant links or updating STP configuration', 'CLI_Command': 'no spanning-tree cost 1000'}
- Step 5: {'Step': '5. Correct VLAN Configuration', 'Action': 'Correct VLAN configuration issues found in step 2', 'CLI_Command': 'vlan 10 name test'}
- Step 6: {'Step': '6. Clear Switch Fabric Congestion', 'Action': 'Clear switch fabric congestion by removing any unnecessary traffic or optimizing switch fabric configuration', 'CLI_Command': 'clear fabric congestion'}

Post-Check Verification

```
show spanning-tree detail
show vlan
show interfaces switchport
show fabric information
```