

Arista Access Switch Alarm SOP - ALARM_4337

Node: Arista-Access-Kolkata-WB-116 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_4337

Description

ALARM_4337 is triggered when a software watchdog timer expires due to a software issue or a hardware problem on the Arista Access Switch.

Potential Root Causes

Cause	Probability
Software watchdog timer expired due to a software issue	High
Software watchdog timer expired due to a hardware problem (e.g., overheating, power issues)	Medium
Misconfigured software watchdog timer	Low

Diagnostic Commands

```
show system internal watchdog timer
show system internal software watchdog timer
show system internal hardware watchdog timer
```

Resolution Steps

- Step 1: {'Step': 'Restart the switch', 'Description': "This may resolve the issue if it's caused by a software problem.", 'Commands': ['request system reboot']}
- Step 2: {'Step': 'Check and replace faulty hardware components', 'Description': 'If the issue is caused by a hardware problem, check and replace faulty components.', 'Commands': ['show hardware', 'show system internal hardware watchdog timer']}
- Step 3: {'Step': 'Reconfigure the software watchdog timer', 'Description': "If the issue is caused by a misconfigured software watchdog timer, reconfigure it according to the vendor's recommendations.", 'Commands': ['config system internal watchdog timer']}

Post-Check Verification

```
show system internal watchdog timer
show system internal software watchdog timer
show system internal hardware watchdog timer
```