

Standard Operating Procedure for Resolving Major Alarm ALARM_1068 on Arista Access Switch Arista-Access-Kolkata-WB-120

Node: Arista-Access-Kolkata-WB-120 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_1068

Description

Alarm ALARM_1068 indicating a major issue on Arista-Access-Kolkata-WB-120, requires immediate attention to prevent network disruption.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Configuration Issue	Medium
Environmental Factors (Temperature, Power)	Low

Diagnostic Commands

```
show system resource usage
show environment temperature
show switch detail | include Hardware
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the switch', 'Description': 'Power cycle the Arista-Access-Kolkata-WB-120 to reset the switch and resolve any transient issues.'}
- Step 2: {'Step': '2. Inspect hardware components', 'Description': 'Inspect the Arista-Access-Kolkata-WB-120 for any physically visible issues or signs of wear and tear.'}
- Step 3: {'Step': '3. Check software configuration', 'Description': 'Verify the software configuration on the Arista-Access-Kolkata-WB-120 for any inconsistencies or errors.'}
- Step 4: {'Step': '4. Replace faulty hardware (if necessary)', 'Description': 'Replace the faulty hardware component if the issue is hardware-related.'}
- Step 5: {'Step': '5. Reboot the switch', 'Description': 'Reboot the Arista-Access-Kolkata-WB-120 to apply any configuration changes or software updates.'}

Post-Check Verification

```
show system resource usage
```

```
show environment temperature
show switch detail | include Hardware
show version | include Software
```