

Arista Access Switch Alarm SOP - ALARM_3101

Node: Arista-Access-Kolkata-WB-122 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_3101

Description

This SOP outlines the steps to diagnose and resolve the ALARM_3101 error on the Arista Access Switch (Node ID: Arista-Access-Kolkata-WB-122).

Potential Root Causes

Cause	Probability
Invalid VLAN configuration	High
Misconfigured STP settings	Medium
Hardware issue with the switch	Low

Diagnostic Commands

```
show vlan | include ALARM_3101
show spanning-tree | include ALARM_3101
show system internal switch detail | include ALARM_3101
show hardware internal temperature | include ALARM_3101
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': 'Check the VLAN configuration on the switch and verify that it matches the production environment.', 'CLI_Command': 'show vlan'}
- Step 2: {'Step': 'Check STP settings', 'Action': 'Verify that the STP settings on the switch match the production environment and are not misconfigured.', 'CLI_Command': 'show spanning-tree'}
- Step 3: {'Step': 'Check hardware status', 'Action': 'Verify that the switch is operating within its temperature and power limits.', 'CLI_Command': 'show hardware internal temperature'}
- Step 4: {'Step': 'Reset the switch', 'Action': 'If none of the above steps resolve the issue, attempt to reset the switch to its default configuration.', 'CLI_Command': 'reset system'}

Post-Check Verification

```
show vlan | include ALARM_3101
show spanning-tree | include ALARM_3101
show system internal switch detail | include ALARM_3101
show hardware internal temperature | include ALARM_3101
```