

Arista Access Switch Alarm Resolution SOP - ALARM_2731

Node: Arista-Access-Mumbai-MH-44 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_2731

Description

This SOP outlines the steps to resolve a Minor alarm ALARM_2731 on the Arista Access Switch Node ID: Arista-Access-Mumbai-MH-44.

Potential Root Causes

Cause	Probability
Misconfigured VLAN	Medium
VLAN Trunk Encapsulation mismatch	Low
Switch software issues	High

Diagnostic Commands

```
show vlan
show interface status
show interface detail
show system switchover history
show system switchover status
```

Resolution Steps

- Step 1: {'Step': 'Verify the VLAN configuration', 'Description': "Run the command 'show vlan' to check the VLAN configuration on the switch", 'Resolution': "Run 'show vlan' and verify the VLAN configuration is correct."}
- Step 2: {'Step': 'Check the VLAN Trunk Encapsulation', 'Description': "Run the command 'show interface status' to check the VLAN Trunk Encapsulation", 'Resolution': "Run 'show interface status' and verify the VLAN Trunk Encapsulation is correct."}
- Step 3: {'Step': 'Restart the switch', 'Description': 'Restart the switch to resolve software issues', 'Resolution': "Run 'reboot' to restart the switch."}

Post-Check Verification

```
show vlan
show interface status
```

```
show interface detail
```