

Standard Operating Procedure: Troubleshooting ALARM_8519 on Arista-Access-Mumbai-MH-44

Node: Arista-Access-Mumbai-MH-44 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_8519

Description

This SOP outlines the steps to troubleshoot and resolve ALARM_8519, a Warning severity alarm on Arista-Access-Mumbai-MH-44, an Access Switch from Arista.

Potential Root Causes

Cause	Probability
High CPU utilization	High
Insufficient Memory	Medium
Misconfigured Spanning Tree Protocol (STP)	Low

Diagnostic Commands

```
show system resources
show memory
show spanning-tree detail
show interface status
show ip traffic
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU usage and memory availability', 'Description': "Run 'show system resources' and 'show memory' commands to check CPU utilization and memory availability.", 'Actions': ['If CPU utilization is high, consider upgrading the CPU or optimizing the system configuration.', 'If memory is insufficient, consider adding more memory or optimizing the system configuration.']}
- Step 2: {'Step': 'Verify STP configuration', 'Description': "Run 'show spanning-tree detail' command to verify STP configuration.", 'Actions': ['If STP is misconfigured, correct the configuration and verify the fix.']}
- Step 3: {'Step': 'Verify interface status', 'Description': "Run 'show interface status' command to verify interface status.", 'Actions': ['If an interface is down, bring it up and verify the fix.']}
- Step 4: {'Step': 'Verify IP traffic', 'Description': "Run 'show ip traffic' command to verify IP traffic.", 'Actions': ['If IP traffic is high, consider optimizing the system configuration or adding more resources.']}

Post-Check Verification

```
show system resources
show memory
show spanning-tree detail
show interface status
show ip traffic
```