

Arista Access Switch Mumbai Alarm SOP - ALARM_8637

Node: Arista-Access-Mumbai-MH-44 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_8637

Description

This Standard Operating Procedure outlines the steps to diagnose and resolve the ALARM_8637 warning on Arista Access Switch Mumbai-MH-44.

Potential Root Causes

Cause	Probability
Buffer Overrun due to High Traffic Volume	High
Misconfigured VLANs or VTP Settings	Medium
Hardware or Software Issue with the Switch	Low

Diagnostic Commands

```
show system internal errorlog
show version
show vlan
show vtp status
```

Resolution Steps

- Step 1: {'Step': '1. Check System Logs for Errors', 'Action': 'Run command: show system internal errorlog'}
- Step 2: {'Step': '2. Verify Switch Software Version', 'Action': 'Run command: show version'}
- Step 3: {'Step': '3. Review VLAN Configuration', 'Action': 'Run command: show vlan'}
- Step 4: {'Step': '4. Check VTP Settings', 'Action': 'Run command: show vtp status'}
- Step 5: {'Step': '5. Clear Buffer Overrun (if applicable)', 'Action': 'Run command: clear buffers'}
- Step 6: {'Step': '6. Reboot the Switch (if applicable)', 'Action': 'Run command: reload'}

Post-Check Verification

```
show system internal errorlog
show version
```

```
show vlan
show vtp status
```