

Troubleshooting SOP for ALARM_1065 on Arista Access Switch

Node: Arista-Access-Mumbai-MH-48 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_1065

Description

ALARM_1065: Critical alarm indicating a failure in the hardware or software of the Arista Access Switch. This SOP outlines the steps to identify and resolve the root cause of the alarm.

Potential Root Causes

Cause	Probability
Hardware Failure (CPU or Memory)	High
Software Bugs or Incompatibilities	Medium
Configuration Issues or Inconsistencies	Low

Diagnostic Commands

```
show system resource
show version
show tech-support
```

Resolution Steps

Step 1: {'Step': 'Restart the switch', 'Description': 'Perform a cold restart of the switch to clear any transient issues.', 'CLI_Command': 'reload'}

Step 2: {'Step': 'Check configuration for inconsistencies', 'Description': 'Verify that the switch configuration is correct and consistent.', 'CLI_Command': 'show running-config'}

Step 3: {'Step': 'Update software to the latest version', 'Description': 'Upgrade the switch software to the latest version available.', 'CLI_Command': 'no boot system; boot system flash:packages/current/'}

Step 4: {'Step': 'Replace faulty hardware components', 'Description': 'Replace any faulty CPU, memory, or other hardware components identified as the root cause of the alarm.', 'CLI_Command': 'N/A'}

Post-Check Verification

```
show system resource
show version
show tech-support
```