

Alarm Resolution for ALARM_9330 on Arista-Access-Mumbai-MH-48

Node: Arista-Access-Mumbai-MH-48 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_9330

Description

This SOP outlines the steps to resolve the ALARM_9330 (Warning) on Arista-Access-Mumbai-MH-48 (Arista Access Switch).

Potential Root Causes

Cause	Probability
Port Link Down	High
Buffer Overruns	Medium
Switch Software Issues	Low

Diagnostic Commands

```
show interface | i ALARM_9330
show interface | i Link
show system internal buffer | i Overrun
```

Resolution Steps

- Step 1: Step 1: Check for any physical issues with the cable or port
- Step 2: {'Step 2': "Verify the link status on the interface using the command 'show interface | i Link'", 'Action': 'Check the link status and correct any configuration issues if necessary'}
- Step 3: {'Step 3': "Check for buffer overruns using the command 'show system internal buffer | i Overrun'", 'Action': "Clear any buffer overruns using the command 'clear system internal buffer'"}
- Step 4: {'Step 4': 'Check for switch software issues', 'Action': 'Upgrade the switch software to the latest version if necessary'}

Post-Check Verification

```
show interface | i ALARM_9330
show system internal buffer | i Overrun
```