

Arista Access Switch Mumbai SOP for Alarm Code ALARM_2594

Node: Arista-Access-Mumbai-MH-54 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_2594

Description

This Standard Operating Procedure outlines the steps to diagnose and resolve the ALARM_2594 on the Arista Access Switch Mumbai-MH-54.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Spanning Tree Protocol (STP) Flaps	High
Misconfigured VLANs or VTP	Medium
Hardware Failure or Aging Issues	Low

Diagnostic Commands

```
show system resources cpu utilization
show spanning-tree detail
show vlan brief
show vtp status
show interfaces status
```

Resolution Steps

Step 1: {'Step': '1. Check STP Flaps', 'Action': "Check the STP flaps using the command 'show spanning-tree detail' and identify the root cause.", 'CLI_Commands': ['clear spanning-tree config', 'no spanning-tree vlan 100']}

Step 2: {'Step': '2. Verify VLAN Configuration', 'Action': "Verify VLAN configuration using the command 'show vlan brief' and identify any misconfigurations.", 'CLI_Commands': ['vlan 100', 'no vlan 100']}

Step 3: {'Step': '3. Check VTP Configuration', 'Action': "Verify VTP configuration using the command 'show vtp status' and identify any misconfigurations.", 'CLI_Commands': ['vtp mode transparent', 'vtp mode client']}

Post-Check Verification

```
show system resources cpu utilization
show spanning-tree detail
```

```
show vlan brief  
show vtp status
```