

Troubleshooting SOP for Arista Access Switch

ALARM_4097: Major Alarm

Node: Arista-Access-Mumbai-MH-54 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_4097

Description

The ALARM_4097 is typically raised when the system detects a major issue with the access switch configuration or hardware. This SOP outlines the steps to troubleshoot and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured interface settings	High
Hardware failure in the access switch	Medium
Incompatible software version	Low

Diagnostic Commands

```
show system resources
show interface status
show version
show tech-support
debug platform software
```

Resolution Steps

Step 1: {'Step': '1. Verify interface settings', 'Action': "Run the command 'show interface status' to check if any interfaces are misconfigured."}

Step 2: {'Step': '2. Check system resources', 'Action': "Run the command 'show system resources' to check if there are any resource-related issues."}

Step 3: {'Step': '3. Check hardware status', 'Action': "Run the command 'show hardware status' to check if there are any hardware issues."}

Step 4: {'Step': '4. Upgrade software version', 'Action': "Run the command 'arista@Arista-Access-Mumbai-MH-54# upgrade image ' to upgrade the software version."}

Step 5: {'Step': '5. Reboot the access switch', 'Action': "Run the command 'arista@Arista-Access-Mumbai-MH-54# reboot' to reboot the access switch."}

Post-Check Verification

```
show interface status
show system resources
show version
```