

Arista Access Switch Alarm Resolution SOP

Node: Arista-Access-Mumbai-MH-54 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_5571

Description

This SOP outlines the steps to diagnose and resolve the ALARM_5571 issue on the Arista Access Switch node Arista-Access-Mumbai-MH-54.

Potential Root Causes

Cause	Probability
High CPU utilization due to software issues	High
Misconfigured VLAN settings	Medium
Hardware failures	Low

Diagnostic Commands

```
show system resources
show processes cpu
show vlan
show interface status
```

Resolution Steps

Step 1: {'Step': 'Verify system resources and processes', 'Action': "Check the output of 'show system resources' and 'show processes cpu' commands", 'CLI_Commands': ['show system resources', 'show processes cpu']}

Step 2: {'Step': 'Verify VLAN settings', 'Action': "Check the output of 'show vlan' command", 'CLI_Commands': ['show vlan']}

Step 3: {'Step': 'Reset the switch to its default configuration', 'Action': "Use the 'reset system' command to reset the switch to its default configuration", 'CLI_Commands': ['reset system']}

Step 4: {'Step': 'Replace the hardware if necessary', 'Action': 'Replace the hardware if it is faulty', 'CLI_Commands': []}

Post-Check Verification

```
show system resources
show processes cpu
show vlan
show interface status
```