

Arista PE Router - Alarm Resolution SOP

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_2691

Description

Standard Operating Procedure for resolving ALARM_2691 on Arista PE Router
Arista-PE-Mumbai-MH-52

Potential Root Causes

Cause	Probability
Hardware issue with one or more interfaces	Medium
Software bug affecting the interface	Low
Configuration issue with the interface	High

Diagnostic Commands

```
show interface status
show interface detail
show tech-support | include ALARM_2691
debug hardware
```

Resolution Steps

- Step 1: {'Step': 'Check interface configuration and validate it is correct', 'Action': "Verify interface settings using 'show run interface ' command"}
- Step 2: {'Step': 'Verify interface hardware is functioning correctly', 'Action': "Use 'show interface status' and 'show interface detail' commands to inspect interface status"}
- Step 3: {'Step': 'Clear interface counters and statistics', 'Action': "Use 'clear counters' command for the problematic interface"}
- Step 4: {'Step': 'Reload the PE router', 'Action': "Use 'reload' command to restart the PE router"}
- Step 5: {'Step': 'Verify interface status after reload', 'Action': "Use 'show interface status' and 'show interface detail' commands to inspect interface status"}

Post-Check Verification

```
show interface status
show interface detail
show tech-support | include ALARM_2691
```