

Arista PE Router Alarm Resolution SOP - ALARM_2973

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_2973

Description

Minor alarm triggered on Arista PE router (Arista-PE-Mumbai-MH-52) indicating a potential issue. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Interface Flapping	High
Hardware Failure	Medium
Software Bug	Low

Diagnostic Commands

```
show interface status
show interface detail
show hardware cpu usage
show system internal forwarding-table
```

Resolution Steps

- Step 1: {'Step': '1. Check interface status and detail', 'Action': "Run the command 'show interface status' and 'show interface detail' to verify the interface status and any error messages."}
- Step 2: {'Step': '2. Verify CPU usage and forwarding table', 'Action': "Run the command 'show hardware cpu usage' and 'show system internal forwarding-table' to check for any CPU usage issues or forwarding table inconsistencies."}
- Step 3: {'Step': '3. Check hardware logs for any hardware failure', 'Action': "Run the command 'show system internal hardware log' to check for any hardware failure or error messages."}
- Step 4: {'Step': '4. Reload the PE router', 'Action': "Run the command 'reload' to restart the PE router and resolve any software bug issues."}

Post-Check Verification

```
show interface status
show interface detail
```

```
show hardware cpu usage  
show system internal forwarding-table
```