

Arista PE Router Alarm SOP: ALARM_3034

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_3034

Description

Minor Alarm on Arista PE Router (Arista-PE-Mumbai-MH-52) due to unknown reason.

Potential Root Causes

Cause	Probability
Hardware Failure	Medium
Software Bug	Low
Misconfigured Interface	High

Diagnostic Commands

```
show system internal alarm details
show interface status
show ip bgp summary
debug hardware health
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Check interface configuration and ensure it matches the expected settings.', 'CLI_Commands': ['show run | include interface', 'show interface detail']}
- Step 2: {'Step': 2, 'Action': 'Verify hardware health and ensure there are no critical failures.', 'CLI_Commands': ['show hardware health', 'debug hardware health']}
- Step 3: {'Step': 3, 'Action': 'Check software image version and ensure it is up-to-date.', 'CLI_Commands': ['show version', 'install -archive activate']}

Post-Check Verification

```
show system internal alarm details
show interface status
show ip bgp summary
show hardware health
```