

Arista PE Router Alarm SOP for ALARM_4100

Node: Arista-PE-Mumbai-MH-52 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_4100

Description

This Standard Operating Procedure outlines the steps to diagnose and resolve the ALARM_4100 on Arista PE Router (Arista-PE-Mumbai-MH-52).

Potential Root Causes

Cause	Probability
Hardware Failure in one of the line cards	High
Software Bug or misconfiguration	Medium
Environmental issues such as overheating	Low

Diagnostic Commands

```
show version
show log | include ALARM_4100
show system resources
show interface status
```

Resolution Steps

- Step 1: {'Step': '1. Check system logs for any error messages related to ALARM_4100', 'Action': "Run 'show log | include ALARM_4100' command"}
- Step 2: {'Step': '2. Verify system resources and check for any issues', 'Action': "Run 'show system resources' command"}
- Step 3: {'Step': '3. Replace the faulty line card if hardware failure is suspected', 'Action': "Run 'no shutdown' command on the new line card"}
- Step 4: {'Step': '4. Reboot the router to clear any software issues', 'Action': "Run 'reload' command"}

Post-Check Verification

```
show log | include ALARM_4100
show system resources
show interface status
show version
```