

Standard Operating Procedure for Minor Alarm

ALARM_4858 on Cisco Access Switch

Cisco-Access-Bangalore-KA-60

Node: Cisco-Access-Bangalore-KA-60 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_4858

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for Minor Alarm ALARM_4858 on Cisco Access Switch Cisco-Access-Bangalore-KA-60.

Potential Root Causes

Cause	Probability
Incorrect VLAN configuration	Medium
Misconfigured STP protocol	High
Incompatible firmware versions	Low

Diagnostic Commands

```
show spanning-tree vlan detail
show vlan brief
show interface status
show run | include vlan
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': "Check VLAN configuration on the switch using the command 'show vlan brief'."}
- Step 2: {'Step': 'Correct VLAN configuration', 'Action': "Use the command 'vlan ' to create the VLAN, then use the command 'vlan interface ' to assign the interface to the VLAN."}
- Step 3: {'Step': 'Verify STP protocol configuration', 'Action': "Use the command 'show spanning-tree vlan detail' to verify the STP protocol configuration."}
- Step 4: {'Step': 'Correct STP protocol configuration', 'Action': "Use the command 'spanning-tree vlan protocol ' to correct the STP protocol configuration."}

Post-Check Verification

```
show spanning-tree vlan detail
show vlan brief
```

```
show interface status
```