

Standard Operating Procedure for Resolving ALARM_3681 on Cisco-Access-Bangalore-KA-80

Node: Cisco-Access-Bangalore-KA-80 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_3681

Description

ALARM_3681: Minor Alarm on Cisco Access Switch Bangalore KA-80. This alarm indicates a minor issue with the switch's performance.

Potential Root Causes

Cause	Probability
Buffer Overrun on Switch	High
Misconfigured Interface Settings	Medium
Hardware Failure of Switch Module	Low

Diagnostic Commands

```
show logging | include ALARM_3681
show interface brief | include Error
show system resources | include Buffer
```

Resolution Steps

- Step 1: {'Step': 'Clear the Buffer Overrun', 'Action': "Execute the command 'clear buffer' to clear the buffer overrun on the switch."}
- Step 2: {'Step': 'Verify Interface Settings', 'Action': "Verify the interface settings using the command 'show interface ' to ensure they are correctly configured."}
- Step 3: {'Step': 'Replace Switch Module (if necessary)', 'Action': "Replace the switch module if it's faulty, and ensure it's properly seated and powered."}

Post-Check Verification

```
show logging | include ALARM_3681
show interface brief | include Error
show system resources | include Buffer
```