

Cisco-Access-Chennai-TN-100 Minor Alarm SOP (ALARM_1009)

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_1009

Description

This SOP outlines the steps to diagnose and resolve the minor alarm ALARM_1009 on the Cisco Access Switch, Node ID: Cisco-Access-Chennai-TN-100.

Potential Root Causes

Cause	Probability
Incorrect spanning tree configuration	Medium
Loopback issue on a port	Low
STP protocol error	High

Diagnostic Commands

```
show spanning-tree summary
show spanning-tree detail
show interface status
show interface counters
show dot1d stp detail
```

Resolution Steps

- Step 1: {'Step': 'Verify spanning tree configuration', 'Action': 'Run the command `show spanning-tree summary` to check for any anomalies in the spanning tree topology.'}
- Step 2: {'Step': 'Check for loopback issue on a port', 'Action': 'Run the command `show interface status` to check for any link errors or loopbacks.'}
- Step 3: {'Step': 'Clear STP protocol errors', 'Action': 'Run the command `clear spanning-tree counters` to clear any STP protocol errors.'}
- Step 4: {'Step': 'Verify STP protocol status', 'Action': 'Run the command `show spanning-tree detail` to verify that the STP protocol is stable.'}

Post-Check Verification

```
show spanning-tree summary
show spanning-tree detail
```

```
show interface status
```