

Cisco Access Switch Chennai TN 100 Alarm Response SOP (ALARM_6502)

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_6502

Description

Warning Alarm Triggered on Cisco-Access-Chennai-TN-100 (Role: Access Switch, Vendor: Cisco)

Potential Root Causes

Cause	Probability
High CPU utilization due to frequent MAC address changes	High
Incorrect VLAN configuration	Medium
STP (Spanning Tree Protocol) issues	Low

Diagnostic Commands

```
show processes cpu | include CPU
show mac address-table | include count
show vlan | include active
show spanning-tree summary
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU utilization and identify the cause', 'Action': 'Run command: show processes cpu | include CPU', 'CLI_Command': 'cpu-processes'}
- Step 2: {'Step': 'Check for frequent MAC address changes', 'Action': 'Run command: show mac address-table | include count', 'CLI_Command': 'mac-address-table'}
- Step 3: {'Step': 'Verify VLAN configuration', 'Action': 'Run command: show vlan | include active', 'CLI_Command': 'vlan-active'}
- Step 4: {'Step': 'Check for STP issues', 'Action': 'Run command: show spanning-tree summary', 'CLI_Command': 'spanning-tree-summary'}
- Step 5: {'Step': 'Adjust the VLAN configuration if necessary', 'Action': 'Use command: vlan vlan-id', 'CLI_Command': 'vlan-adjustment'}
- Step 6: {'Step': 'Adjust the spanning tree configuration if necessary', 'Action': 'Use command: spanning-tree vlan vlan-id', 'CLI_Command': 'spanning-tree-adjustment'}

Post-Check Verification

```
show processes cpu | include CPU
show mac address-table | include count
show vlan | include active
show spanning-tree summary
```