

Alarm Resolution SOP for Cisco Access Switch Chennai TN-100 (ALARM_9815)

Node: Cisco-Access-Chennai-TN-100 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_9815

Description

This SOP outlines the steps to diagnose and resolve the ALARM_9815 on the Cisco Access Switch Chennai TN-100, a major alarm indicating a critical issue with the switch.

Potential Root Causes

Cause	Probability
CPU utilization exceeds 90%	High
Memory leak due to software bug	Medium
Physical or logical port failure	Low

Diagnostic Commands

```
show process cpu sorted
show memory | include Total
show controllers cpu utilization
show interfaces transceiver
```

Resolution Steps

- Step 1: {'Step': '1. Reboot the switch', 'Action': "Enter the command 'reload' in privileged EXEC mode to reboot the switch."}
- Step 2: {'Step': '2. Check CPU utilization', 'Action': "Enter the command 'show process cpu sorted' to verify CPU utilization. If it's still high, proceed to step 3.", 'CLI_Commands': ['show process cpu sorted']}
- Step 3: {'Step': '3. Check memory usage', 'Action': "Enter the command 'show memory | include Total' to verify memory usage. If it's still high, proceed to step 4.", 'CLI_Commands': ['show memory | include Total']}
- Step 4: {'Step': '4. Check for memory leaks', 'Action': "Enter the command 'show memory leaks' to identify the memory leaks. If found, proceed to step 5.", 'CLI_Commands': ['show memory leaks']}
- Step 5: {'Step': '5. Replace the faulty component', 'Action': 'Identify and replace the faulty component based on the root cause identified.'}
- Step 6: {'Step': '6. Verify the fix', 'Action': "Enter the command 'show controllers cpu utilization' to verify CPU utilization and 'show interfaces transceiver' to verify port status."}

Post-Check Verification

```
show controllers cpu utilization  
show interfaces transceiver
```