

Cisco-Access-Chennai-TN-104 SOP for ALARM_5885

Node: Cisco-Access-Chennai-TN-104 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_5885

Description

ALARM_5885 indicates a critical issue on Cisco-Access-Chennai-TN-104, an Access Switch from Cisco. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
High CPU utilization	High
Stacking issues between Cisco-Access-Chennai-TN-104 and neighboring switches	Medium
Misconfigured VLANs or spanning-tree settings	Low

Diagnostic Commands

```
show processes cpu sorted
show spanning-tree detail
show vlan brief
show interface status
show stack details
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and process utilization', 'Action': "Run the command 'show processes cpu sorted' to determine which process is consuming the most CPU resources."}
- Step 2: {'Step': '2. Verify stacking configuration', 'Action': "Run the command 'show stack details' to verify the stacking configuration between Cisco-Access-Chennai-TN-104 and neighboring switches."}
- Step 3: {'Step': '3. Check VLAN and spanning-tree configuration', 'Action': "Run the command 'show vlan brief' to verify VLAN configuration and the command 'show spanning-tree detail' to verify spanning-tree settings."}
- Step 4: {'Step': '4. Check interface status', 'Action': "Run the command 'show interface status' to verify the status of all interfaces on Cisco-Access-Chennai-TN-104."}
- Step 5: {'Step': '5. Resolve stacking issues or misconfigured VLANs or spanning-tree settings', 'Action': 'Correct any stacking issues, misconfigured VLANs, or spanning-tree settings based on the diagnostic results.'}

Post-Check Verification

```
show processes cpu sorted
show spanning-tree detail
show vlan brief
show interface status
```