

Cisco Access Switch Chennai TN 106 Alarm Resolution SOP (ALARM_2985)

Node: Cisco-Access-Chennai-TN-106 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_2985

Description

This SOP outlines the steps to diagnose and resolve the {{alarm_code}} alarm on the Cisco Access Switch Chennai TN 106.

Potential Root Causes

Cause	Probability
Misconfigured VLAN settings	Medium
Faulty or malfunctioning network interface card (NIC)	High
Cable or connection issue between the switch and the network	Medium
Overheating of the switch or its components	Low

Diagnostic Commands

```
show int status
show vlan
show system resources
show environment
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Verify VLAN settings', 'Action': "Check the VLAN configuration on the switch using the 'show vlan' command. Verify that the VLAN settings are correct and match the network design."}
- Step 2: {'Step': '2. Check network interface card (NIC) status', 'Action': "Use the 'show int status' command to verify the status of the NIC. If the NIC is malfunctioning, replace it with a new one."}
- Step 3: {'Step': '3. Check cables and connections', 'Action': "Verify that all cables and connections between the switch and the network are secure and functioning properly."}
- Step 4: {'Step': '4. Check switch temperature', 'Action': "Use the 'show environment' command to check the switch temperature. If the temperature is high, allow the switch to cool down or replace it with a new one."}

Step 5: {'Step': '5. Run tech-support', 'Action': "Run the 'show tech-support' command to gather detailed information about the switch. This can be used for further analysis and troubleshooting."}

Post-Check Verification

```
show vlan
show int status
show system resources
```