

SOP: Resolving ALARM_6985 on Cisco-Access-Chennai-TN-106

Node: Cisco-Access-Chennai-TN-106 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_6985

Description

Highly Critical Alarm on Cisco-Access-Chennai-TN-106: ALARM_6985. This alarm indicates a potential hardware failure or software corruption on the Access Switch.

Potential Root Causes

Cause	Probability
Hardware Failure (Power Supply or Fan)	High
Software Corruption (IOS Image or Configuration)	Medium
Environmental Factors (Temperature or Humidity)	Low

Diagnostic Commands

```
show environment
show power consumption
show tech-support
debug switch 1
debug switch 2
```

Resolution Steps

- Step 1: {'Step': 'Power Cycle the Switch', 'Description': 'Cycle the power on the Cisco-Access-Chennai-TN-106 to ensure a clean boot.'}
- Step 2: {'Step': 'Verify Hardware Components', 'Description': 'Inspect the power supply and fan units for any signs of physical damage or malfunction.'}
- Step 3: {'Step': 'Reload the IOS Image', 'Description': 'Reload the IOS image using the command "reload" to rule out software corruption.'}
- Step 4: {'Step': 'Verify Configuration', 'Description': 'Verify the configuration of the Access Switch using the command "show running-config" to ensure no errors or inconsistencies.'}
- Step 5: {'Step': 'Check Environmental Factors', 'Description': 'Verify the temperature and humidity levels in the area around the Access Switch to ensure they are within recommended ranges.'}

Post-Check Verification

```
show version
show running-config
show environment
show power consumption
debug switch 1
```