

SOP: Resolving Alarm ALARM_1024 on Cisco Access Switch Chennai-TN-108

Node: Cisco-Access-Chennai-TN-108 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_1024

Description

The Alarm ALARM_1024 on Cisco Access Switch Chennai-TN-108 is triggered due to a major issue, and this SOP outlines the steps to diagnose and resolve the problem.

Potential Root Causes

Cause	Probability
Interface Flapping	High
Spanning Tree Protocol (STP) Loop	Medium
Hardware Failure	Low

Diagnostic Commands

```
show interfaces | include FLAPPING
show spanning-tree detail
show module | include Temperature
```

Resolution Steps

- Step 1: {'Step': 'Verify interface status and configure speed and duplex settings', 'Action': "Enter the command 'show interfaces ' to verify the interface status. Configure speed and duplex settings using the command ' speed duplex '"}}
- Step 2: {'Step': 'Check STP topology and remove any loops', 'Action': "Enter the command 'show spanning-tree detail' to verify STP topology. Remove any loops by configuring the command ' spanning-tree portfast'"}}
- Step 3: {'Step': 'Replace hardware if necessary', 'Action': "Check the temperature of the module using the command 'show module | include Temperature'. If the temperature is high, replace the hardware module."}]}

Post-Check Verification

```
show interfaces
show spanning-tree detail
show module
```