

Standard Operating Procedure for Resolving Alarm ALARM_5070 on Cisco-Access-Chennai-TN-96 Access Switch

Node: Cisco-Access-Chennai-TN-96 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_5070

Description

Alarm ALARM_5070 indicates a minor issue on the Cisco-Access-Chennai-TN-96 access switch, which may be caused by a misconfigured VLAN or a spanning tree topology issue.

Potential Root Causes

Cause	Probability
Misconfigured VLAN	High
Spanning Tree Topology Issue	Medium
Software Bug	Low

Diagnostic Commands

```
show vlan
show spanning-tree
show interface status
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Check the VLAN configuration', 'Action': 'Verify the VLAN configuration using the show vlan command. If the VLAN is misconfigured, correct the configuration.', 'CLI_Commands': 'no vlan '}
- Step 2: {'Step': '2. Review the spanning tree topology', 'Action': 'Verify the spanning tree topology using the show spanning-tree command. If the topology is incorrect, rectify the issue.', 'CLI_Commands': 'spanning-tree vlan root primary'}
- Step 3: {'Step': '3. Reload the switch', 'Action': 'Reload the switch to clear any software bugs. This may resolve the issue.', 'CLI_Commands': 'reload'}

Post-Check Verification

```
show vlan
show spanning-tree
```

```
show interface status
show tech-support
```