

SOP for Resolving ALARM_7990 on Cisco Access Switch - Cisco-Access-Delhi-NCR-16

Node: Cisco-Access-Delhi-NCR-16 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_7990

Description

ALARM_7990 indicates a critical issue on the Cisco Access Switch. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Spanning Tree Protocol (STP) Flap	High
Misconfigured VLAN or Trunk Interface	Medium
Hardware Failure due to Overheating or Power Issues	Low

Diagnostic Commands

```
show spanning-tree detail
show interface trunk
show version
show env all
show power inline
```

Resolution Steps

- Step 1: {'Step': '1. Check and clear STP flap', 'Description': "Use the command 'clear spanning-tree counters' to clear the STP flap counters.", 'Command': 'clear spanning-tree counters'}
- Step 2: {'Step': '2. Verify VLAN and Trunk Interface Configuration', 'Description': "Use the command 'show vlan' and 'show interface trunk' to verify the configuration.", 'Command': 'show vlan; show interface trunk'}
- Step 3: {'Step': '3. Check and replace faulty hardware (if applicable)', 'Description': "Use the command 'show env all' and 'show power inline' to check for hardware issues.", 'Command': 'show env all; show power inline'}
- Step 4: {'Step': '4. Restart the switch (if applicable)', 'Description': "Use the command 'reload' to restart the switch.", 'Command': 'reload'}

Post-Check Verification

```
show spanning-tree detail
```

```
show interface trunk
show version
show env all
show power inline
```