

Standard Operating Procedure: Resolving ALARM_7252 on Cisco-Access-Kolkata-WB-112

Node: Cisco-Access-Kolkata-WB-112 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_7252

Description

This SOP outlines the step-by-step process to resolve ALARM_7252 (Minor) on Cisco-Access-Kolkata-WB-112, an Access Switch from Cisco.

Potential Root Causes

Cause	Probability
Invalid VLAN configuration	Medium
Spanning Tree issues due to misconfigured ports	High
Interface flap due to hardware or software issues	Low

Diagnostic Commands

```
show vlan
show spanning-tree
show interfaces status
show interfaces switchport
```

Resolution Steps

- Step 1: {'Step': '1. Check VLAN configuration and configure correctly if needed', 'Action': 'configure terminal\nvlan \nexit\n'}
- Step 2: {'Step': '2. Check and correct Spanning Tree configuration if necessary', 'Action': 'configure terminal\nspanning-tree vlan root primary\nexit\n'}
- Step 3: {'Step': '3. Check interface status and flap history', 'Action': 'show interfaces status\nshow interfaces switchport\n'}
- Step 4: {'Step': '4. Reset the interface if necessary', 'Action': 'interface \nshutdown\nno shutdown\nexit\n'}

Post-Check Verification

```
show vlan
show spanning-tree
show interfaces status
```

```
show interfaces switchport
```