

SOP: Resolving Critical Alarm ALARM_3261 on Cisco-Access-Mumbai-MH-38

Node: Cisco-Access-Mumbai-MH-38 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_3261

Description

This SOP outlines the steps to resolve Critical Alarm ALARM_3261 on Cisco-Access-Mumbai-MH-38, a Cisco Access Switch in Mumbai, India.

Potential Root Causes

Cause	Probability
High CPU Utilization due to spanning tree topology changes	High
Misconfigured VLANs or trunk links	Medium
Hardware or software issues with the switch	Low

Diagnostic Commands

```
show spanning-tree root
show spanning-tree vlan
show int switchport
show int status
show system resources
```

Resolution Steps

- Step 1: {'Step': '1. Check for spanning tree topology changes', 'Action': 'Verify if there have been any changes to the spanning tree topology recently. If yes, check the show spanning-tree root command for any issues.'}
- Step 2: {'Step': '2. Verify VLAN configuration', 'Action': 'Use the show int switchport command to verify VLAN configuration. If misconfigured, correct the VLAN configuration.'}
- Step 3: {'Step': '3. Check for hardware or software issues', 'Action': 'Use the show system resources command to check if there are any hardware or software issues with the switch. If yes, contact technical support for further assistance.'}
- Step 4: {'Step': '4. Reset the switch', 'Action': 'If none of the above steps resolve the issue, reset the switch using the reload command.'}

Post-Check Verification

```
show int status
```

```
show system resources
show spanning-tree vlan
```