

Cisco-Access-Mumbai-MH-38 Alarm SOP

(ALARM_7280)

Node: Cisco-Access-Mumbai-MH-38 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_7280

Description

ALARM_7280 is a warning alarm indicating potential issues on Cisco-Access-Mumbai-MH-38, which is a Cisco Access Switch. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Port congestion due to high packet loss	Medium
Misconfigured Spanning Tree Protocol (STP)	High
Incompatible firmware versions	Low

Diagnostic Commands

```
show interface status
show spanning-tree detail
show run | include spanning-tree
show version
```

Resolution Steps

- Step 1: {'Step': 'Check for port congestion and packet loss', 'Action': "Run 'show interface status' command and verify packet loss on the affected port."}
- Step 2: {'Step': 'Verify STP configuration', 'Action': "Run 'show spanning-tree detail' and 'show run | include spanning-tree' commands to verify STP configuration."}
- Step 3: {'Step': 'Update firmware to compatible version', 'Action': "Run 'show version' command to verify firmware version and update to a compatible version if necessary."}

Post-Check Verification

```
show interface status
show spanning-tree detail
show run | include spanning-tree
```