

Cisco Access Switch Mumbai MH-38 Alarm SOP - ALARM_9824

Node: Cisco-Access-Mumbai-MH-38 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_9824

Description

Warning: ALARM_9824 triggered on Cisco Access Switch (Node ID: Cisco-Access-Mumbai-MH-38) due to a potential issue.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Misconfigured QoS Policies	Medium
Hardware Failure	Low

Diagnostic Commands

```
show process cpu | include %Cpu(s)
show quality of service policy-map interface
show interfaces status
```

Resolution Steps

Step 1: {'Step': '1. Check CPU utilization and QoS policies', 'Action': 'Run show process cpu | include %Cpu(s) and show quality of service policy-map interface commands to identify potential issues.'}

Step 2: {'Step': '2. Adjust QoS policies if necessary', 'Action': 'Modify QoS policies using the config t mode and apply the changes using the copy run start command.'}

Step 3: {'Step': '3. Replace hardware if necessary', 'Action': 'Replace the faulty hardware with new one and verify the issue is resolved.'}

Post-Check Verification

```
show process cpu | include %Cpu(s)
show quality of service policy-map interface
show interfaces status
```