

Cisco-Access-Mumbai-MH-40 Minor Alarm Resolution SOP

Node: Cisco-Access-Mumbai-MH-40 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_2464

Description

The Cisco-Access-Mumbai-MH-40 Access Switch has triggered a minor alarm (ALARM_2464) due to a potential issue. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Link flapping between switch and neighboring device	High
Incorrect switch configuration	Medium
Hardware failure (rare)	Low

Diagnostic Commands

```
show spanning-tree detail
show interface brief
show ip int brief
show run
debug stack
```

Resolution Steps

- Step 1: {'Step': 'Verify link status and STP configuration', 'Action': 'Run show spanning-tree detail and show interface brief commands to verify link status and STP configuration.'}
- Step 2: {'Step': 'Check switch configuration', 'Action': 'Run show run command to check switch configuration and ensure it matches the expected settings.'}
- Step 3: {'Step': 'Reset switch or replace faulty hardware', 'Action': 'Perform a soft or hard reset of the switch, or replace the faulty hardware depending on the root cause.'}
- Step 4: {'Step': 'Verify alarm clearance', 'Action': 'Run show logging privileged command to verify that the alarm has cleared.'}

Post-Check Verification

```
show logging privileged
show alarm detail
```

```
show interface brief  
show ip int brief
```