

Cisco Access Switch SOP: Resolving ALARM_7321 on Node ID: Cisco-Access-Mumbai-MH-40

Node: Cisco-Access-Mumbai-MH-40 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_7321

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve the ALARM_7321, a critical alarm on the Cisco Access Switch in Mumbai, Node ID: Cisco-Access-Mumbai-MH-40.

Potential Root Causes

Cause	Probability
Power supply failure	High
Temperature exceeding threshold	Medium
Fan failure	Low

Diagnostic Commands

```
show environment
show power supply
show fan
show logging
debug platform software
```

Resolution Steps

- Step 1: {'Step': 'Check power supply status', 'Command': 'show power supply', 'Description': "Verify the power supply status to determine if it's the root cause of the alarm."}
- Step 2: {'Step': 'Replace faulty power supply', 'Command': 'no power supply ', 'Description': 'Remove the faulty power supply and replace it with a new one.'}
- Step 3: {'Step': 'Verify fan status', 'Command': 'show fan', 'Description': "Check the fan status to ensure it's functioning properly."}
- Step 4: {'Step': 'Replace faulty fan', 'Command': 'no fan ', 'Description': 'Remove the faulty fan and replace it with a new one.'}
- Step 5: {'Step': 'Verify temperature threshold', 'Command': 'show environment', 'Description': "Check the temperature threshold to ensure it's within the acceptable range."}
- Step 6: {'Step': 'Perform system reboot', 'Command': 'reload', 'Description': 'Reboot the system to ensure the changes take effect.'}

Post-Check Verification

```
show alarm
show environment
show power supply
show fan
show logging
```