

SOP for Resolving ALARM_7742 on Cisco-Access-Mumbai-MH-40

Node: Cisco-Access-Mumbai-MH-40 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_7742

Description

This SOP outlines the steps to resolve the ALARM_7742 (Warning) on Cisco-Access-Mumbai-MH-40, a Cisco Access Switch. The alarm indicates a potential issue with the switch.

Potential Root Causes

Cause	Probability
Incorrect Power Supply Configuration	High
Overheating Issues	Medium
Invalid VLAN Configuration	Low

Diagnostic Commands

```
show power supply detail
show environmental monitoring
show vlan database
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Verify Power Supply Configuration', 'Description': 'Check the power supply configuration on the switch to ensure it is set up correctly.', 'CLI_Command': 'show power supply detail'}
- Step 2: {'Step': 'Reset Power Supply', 'Description': 'Reset the power supply to its default settings.', 'CLI_Command': 'power supply reset'}
- Step 3: {'Step': 'Verify Environmental Monitoring', 'Description': 'Check the environmental monitoring data to see if there are any overheating issues.', 'CLI_Command': 'show environmental monitoring'}
- Step 4: {'Step': 'Configure VLAN Database', 'Description': 'Verify that the VLAN database is correctly configured.', 'CLI_Command': 'show vlan database'}
- Step 5: {'Step': 'Verify Interface Status', 'Description': 'Verify the status of all interfaces on the switch.', 'CLI_Command': 'show interface status'}

Post-Check Verification

```
show power supply detail
show environmental monitoring
show vlan database
show interface status
```