

Cisco Access Switch Minor Alarm Resolution SOP

Node: Cisco-Access-Mumbai-MH-44 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_5781

Description

Resolving minor alarm ALARM_5781 on Cisco Access Switch Node ID: Cisco-Access-Mumbai-MH-44

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Software Crashes	Medium
Environmental Factors (Temperature, Humidity)	Low

Diagnostic Commands

```
show processes cpu sorted
show system resource
show tech-support
```

Resolution Steps

Step 1: {'Step': '1. Monitor CPU Utilization', 'Action': "Run command 'show processes cpu sorted' to monitor CPU utilization and identify resource-intensive processes.", 'CLI_Command': 'show processes cpu sorted'}

Step 2: {'Step': '2. Check Software Crashes', 'Action': "Run command 'show system resource' to check for software crashes and identify potential causes.", 'CLI_Command': 'show system resource'}

Step 3: {'Step': '3. Inspect Environmental Factors', 'Action': 'Verify that environmental factors such as temperature and humidity are within recommended ranges.', 'Action_Type': 'Physical Inspection'}

Step 4: {'Step': '4. Restart Switch', 'Action': 'Restart the switch to resolve the issue.', 'CLI_Command': 'reload'}

Step 5: {'Step': '5. Apply Software Patch (if necessary)', 'Action': 'Apply software patch to resolve software crashes.', 'CLI_Command': 'install system image'}

Post-Check Verification

```
show processes cpu sorted
show system resource
show tech-support
```