

SOP: Troubleshooting ALARM_2159 on Cisco-Access-Mumbai-MH-52

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_2159

Description

This SOP outlines the steps to troubleshoot the ALARM_2159 (Warning) on Cisco-Access-Mumbai-MH-52, a Cisco Access Switch

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or misconfiguration	High
Misconfigured spanning tree protocol (STP) settings	Medium
Incompatible firmware versions on connected devices	Low

Diagnostic Commands

```
show process cpu | exclude System
show spanning-tree summary
show version
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and identify the process causing high utilization', 'Action': "Use the command 'show process cpu | exclude System' to check CPU utilization"}
- Step 2: {'Step': '2. Verify STP settings and adjust as necessary', 'Action': "Use the command 'show spanning-tree summary' to verify STP settings and adjust as necessary"}
- Step 3: {'Step': '3. Verify firmware versions on connected devices', 'Action': "Use the command 'show version' to check firmware versions on connected devices and update if necessary"}
- Step 4: {'Step': '4. Restart the switch if necessary', 'Action': "Use the command 'reload' to restart the switch"}

Post-Check Verification

```
show process cpu | exclude System
show spanning-tree summary
show version
```