

Cisco Access Switch - Alarm Handling for ALARM_2985

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_2985

Description

Handling Minor Severity Alarm ALARM_2985 on Cisco Access Switch, Node ID: Cisco-Access-Mumbai-MH-52

Potential Root Causes

Cause	Probability
Invalid VLAN ID configured on a port	High
Misconfigured Spanning Tree Protocol (STP)	Medium
Hardware malfunction or software issues	Low

Diagnostic Commands

```
show spanning-tree summary
show spanning-tree detail
show vlan brief
show interface switchport
```

Resolution Steps

- Step 1: {'Step': 'Check VLAN configuration on the port', 'Action': "Verify VLAN ID is correct using 'show vlan brief'", 'CLI_Command': 'show vlan brief'}
- Step 2: {'Step': 'Reconfigure VLAN ID on the port', 'Action': "Modify VLAN ID using 'switchport vlan ' command", 'CLI_Command': 'switchport vlan '}
- Step 3: {'Step': 'Verify STP configuration', 'Action': "Check STP status using 'show spanning-tree summary' command", 'CLI_Command': 'show spanning-tree summary'}
- Step 4: {'Step': 'Reconfigure STP (if necessary)', 'Action': "Modify STP configuration using 'spanning-tree vlan ' command", 'CLI_Command': 'spanning-tree vlan '}

Post-Check Verification

```
show spanning-tree summary
show spanning-tree detail
show vlan brief
```

```
show interface switchport
```