

SOP for Resolving ALARM_3290 on Cisco-Access-Mumbai-MH-52 Access Switch

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_3290

Description

Alarm ALARM_3290 is triggered on Cisco-Access-Mumbai-MH-52 indicating a potential issue with the switch's hardware or software configuration.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Misconfigured VLAN or Port Settings	Medium
Software Bug or Firmware Issue	Low

Diagnostic Commands

```
show version
show module
show interface status
show logging
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the switch', 'Description': 'Ensure the switch is properly powered off and then back on to clear any temporary issues.'}
- Step 2: {'Step': '2. Check VLAN and Port Settings', 'Description': "Verify VLAN and port settings are configured correctly using the command 'show vlan' and 'show interface '", 'Commands': ['show vlan', 'show interface ']}
- Step 3: {'Step': '3. Check for Software or Firmware Issues', 'Description': "Verify the switch's software or firmware is up-to-date using the command 'show version'", 'Commands': ['show version']}
- Step 4: {'Step': '4. Replace Faulty Hardware', 'Description': 'If the issue persists, consider replacing the faulty hardware.'}

Post-Check Verification

```
show version
```

```
show module
show interface status
show logging
```