

Alarm Resolution SOP for Cisco Access Switch

ALARM_3657

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_3657

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for ALARM_3657 on Cisco Access Switch Node ID: Cisco-Access-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
Misconfigured Spanning Tree Protocol (STP)	High
Link aggregation group (LAG) configuration issue	Medium
Hardware malfunction or failure	Low

Diagnostic Commands

```
show spanning-tree detail
show interface status
show lacp neighbor detail
show hardware internal temperature
show environment detail
```

Resolution Steps

- Step 1: {'Step': '1. Disable and re-enable the port', 'Description': "Disable the port by issuing the 'shutdown' command and then re-enable it with the 'no shutdown' command.", 'CLI': 'interface GigabitEthernet0/0\nshutdown\nno shutdown'}
- Step 2: {'Step': '2. Verify STP configuration', 'Description': 'Check the STP configuration and ensure it is correctly set up.', 'CLI': 'show spanning-tree detail'}
- Step 3: {'Step': '3. Check LAG configuration', 'Description': 'Verify the LAG configuration and ensure it is correctly set up.', 'CLI': 'show lacp neighbor detail'}
- Step 4: {'Step': '4. Replace hardware if necessary', 'Description': 'If the above steps do not resolve the issue and the hardware is malfunctioning, replace the hardware.'}

Post-Check Verification

```
show spanning-tree detail
```

```
show interface status
show lacp neighbor detail
show hardware internal temperature
```