

Cisco Access Switch Alarm SOP - ALARM_8882

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_8882

Description

Minor alarm on Cisco-Access-Mumbai-MH-52. Alarm description: . Verify switch logs for detailed information.

Potential Root Causes

Cause	Probability
High CPU utilization due to misconfigured QoS policies	High
Inconsistent switch configuration due to human error	Medium
Hardware failure in the switch	Low

Diagnostic Commands

```
show processes cpu history
show running-config | include qos
show boot
show version
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Clear QoS policies and verify if the issue persists', 'Action': 'no qos policy-map '}
- Step 2: {'Step': 'Verify switch configuration and correct any inconsistencies', 'Action': ''}
- Step 3: {'Step': 'Replace the faulty switch or repair hardware as necessary', 'Action': ''}

Post-Check Verification

```
show processes cpu history
show running-config | include qos
show interface status
```