

Standard Operating Procedure for Ericsson Access Switch ALARM_1607 in Bangalore, KA-64

Node: Ericsson-Access-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_1607

Description

Alarm ALARM_1607 is triggered on Ericsson-Access-Bangalore-KA-64 due to minor issues.

Potential Root Causes

Cause	Probability
High CPU utilization on the Access Switch	High
Incorrect configuration of the Access Switch	Medium
Software issues with the Access Switch	Low

Diagnostic Commands

```
admin:show cpu-utilization
admin:show system-status
admin:show configuration
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization and system status', 'Action': "Run the command 'admin:show cpu-utilization' to check CPU utilization and 'admin:show system-status' to check system status"}
- Step 2: {'Step': 'Verify configuration', 'Action': "Run the command 'admin:show configuration' to verify configuration and make necessary changes if required"}
- Step 3: {'Step': 'Restart the Access Switch', 'Action': "Run the command 'admin:restart' to restart the Access Switch"}

Post-Check Verification

```
admin:show cpu-utilization
admin:show system-status
```