

Ericsson Access Switch (Node ID: Ericsson-Access-Bangalore-KA-80) - Alarm Resolution SOP for ALARM_1266 (Critical Severity)

Node: Ericsson-Access-Bangalore-KA-80 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_1266

Description

This SOP outlines the steps to diagnose and resolve the ALARM_1266 (Critical Severity) on the Ericsson Access Switch (Node ID: Ericsson-Access-Bangalore-KA-80).

Potential Root Causes

Cause	Probability
Hardware failure of the Ethernet Interface	High
Software bug in the Ethernet Interface driver	Medium
Misconfigured Ethernet Interface settings	Low

Diagnostic Commands

```
show interface ethernet detail
show interface ethernet stats
show run | include ethernet
show platform software status
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the Ethernet Interface', 'Description': "Power cycle the Ethernet Interface by executing the 'service interface ethernet power-cycle' command."}
- Step 2: {'Step': '2. Check and correct the Ethernet Interface configuration', 'Description': "Verify the Ethernet Interface configuration by executing the 'show run | include ethernet ' command and correct any misconfigurations."}
- Step 3: {'Step': '3. Upgrade the Ethernet Interface driver', 'Description': "Upgrade the Ethernet Interface driver by executing the 'install software package ' command."}

Post-Check Verification

```
show interface ethernet detail
show interface ethernet stats
```

ping