

Ericsson Access Switch Minor Alarm SOP - ALARM_8457

Node: Ericsson-Access-Bangalore-KA-80 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_8457

Description

This SOP outlines the steps to diagnose, resolve and verify a minor alarm on Ericsson Access Switch
Node ID: Ericsson-Access-Bangalore-KA-80, Vendor: Ericsson, Role: Access Switch, Alarm Code: ALARM_8457, Severity: Minor.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Incorrect Configuration	Medium
Software Issues	Low

Diagnostic Commands

```
show system resources
show cpu utilization
show configuration
show alarms
```

Resolution Steps

- Step 1: {'Step': 'Check CPU Utilization', 'Action': "Run 'show cpu utilization' command and compare with baseline values.", 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': 'Verify Configuration', 'Action': "Run 'show configuration' command and verify for any discrepancies.", 'CLI_Command': 'show configuration'}
- Step 3: {'Step': 'Update Software', 'Action': 'Update the software to latest version and restart the switch.', 'CLI_Command': 'software install --force'}
- Step 4: {'Step': 'Clear Alarms', 'Action': "Clear the alarms using 'clear alarms' command.", 'CLI_Command': 'clear alarms'}

Post-Check Verification

```
show system resources
show cpu utilization
```

```
show configuration
show alarms
```