

Ericsson Access Switch - ALARM_9351 - Major Alarm Resolution SOP

Node: Ericsson-Access-Bangalore-KA-80 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_9351

Description

This SOP outlines the steps to diagnose and resolve the ALARM_9351 - 'Major Alarm' on Ericsson Access Switch located at Bangalore-KA-80.

Potential Root Causes

Cause	Probability
Optical Module Failure	High
Cable Fault	Medium
Hardware Issue	Low

Diagnostic Commands

```
show optics
show cable-diagnostic
show system hardware
```

Resolution Steps

Step 1: { 'Step': '1. Check Optical Module Status', 'Action': "Verify the optical module status using 'show optics' command.", 'Command': 'show optics' }

Step 2: { 'Step': '2. Check Cable Fault', 'Action': "Use 'show cable-diagnostic' command to check for any cable faults.", 'Command': 'show cable-diagnostic' }

Step 3: { 'Step': '3. Check Hardware Status', 'Action': "Verify the hardware status using 'show system hardware' command.", 'Command': 'show system hardware' }

Step 4: { 'Step': '4. Replace Optical Module', 'Action': 'Replace the optical module if it is faulty.', 'Command': 'no optics ' }

Step 5: { 'Step': '5. Replace Cable', 'Action': 'Replace the cable if it is faulty.', 'Command': 'no cable ' }

Post-Check Verification

```
show optics
show cable-diagnostic
```

```
show system hardware
```