

Ericsson Access Switch Alarm SOP: ALARM_5811

Node: Ericsson-Access-Bangalore-KA-84 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_5811

Description

This SOP outlines the procedures to be followed when the Ericsson Access Switch at Bangalore KA-84 (Node ID: Ericsson-Access-Bangalore-KA-84) triggers a minor alarm with Alarm Code ALARM_5811.

Potential Root Causes

Cause	Probability
Hardware failure in the Access Switch	High
Software issue in the Access Switch	Medium
Misconfiguration of the Access Switch	Low

Diagnostic Commands

```
show alarm
show log
show interfaces
show controllers
```

Resolution Steps

- Step 1: {'Step': 'Restart the Access Switch', 'Action': 'execute reset', 'Note': 'This may resolve the issue if it is due to a software glitch.'}
- Step 2: {'Step': 'Check and replace faulty hardware components', 'Action': 'show controllers | include Faulty', 'Note': 'Identify and replace any faulty hardware components.'}
- Step 3: {'Step': 'Reconfigure the Access Switch', 'Action': 'configure terminal\ninterface \nno shutdown', 'Note': 'Reconfigure the Access Switch to the recommended settings.'}

Post-Check Verification

```
show alarm
show log
show interfaces
show controllers
```