

Ericsson-Access-Bangalore-KA-84 ALARM_6319 SOP

Node: Ericsson-Access-Bangalore-KA-84 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6319

Description

This SOP describes the steps to mitigate the ALARM_6319 condition on Ericsson Access Switch Node ID Ericsson-Access-Bangalore-KA-84.

Potential Root Causes

Cause	Probability
Hardware failure in the radio unit	High
Software bug in the radio unit software	Medium
Configuration mismatch between radio unit and the Access Switch	Low

Diagnostic Commands

```
show radio-unit status
show radio-unit alarms
show configuration radio-unit
show statistics radio-unit
```

Resolution Steps

- Step 1: {'Step': 'Verify the radio unit status and alarms', 'Action': "Run the command 'show radio-unit status' and 'show radio-unit alarms' to identify the root cause of the alarm.", 'CLI_Commands': ['show radio-unit status', 'show radio-unit alarms']}
- Step 2: {'Step': 'Check the radio unit configuration', 'Action': "Run the command 'show configuration radio-unit' to verify that the configuration is correct.", 'CLI_Commands': ['show configuration radio-unit']}
- Step 3: {'Step': 'Swap the radio unit', 'Action': 'Swap the faulty radio unit with a spare one and reboot the Access Switch.', 'CLI_Commands': ['radio-unit swap ', 'reboot']}
- Step 4: {'Step': 'Revert the configuration', 'Action': 'Revert the configuration change if any, to the previous stable version.', 'CLI_Commands': ['configuration revert']}

Post-Check Verification

```
show radio-unit status
show radio-unit alarms
```

```
show configuration radio-unit  
show statistics radio-unit
```