

Standard Operating Procedure for Ericsson Access Node Bangalore KA-84 Alarm 7788

Node: Ericsson-Access-Bangalore-KA-84 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_7788

Description

This SOP is designed to handle a Major alarm on Ericsson Access Node Bangalore KA-84, specifically the ALARM_7788.

Potential Root Causes

Cause	Probability
Hardware Failure in Line Card	High
Software Bug in Node OS	Medium
Incorrect Configuration	Low

Diagnostic Commands

```
show tech support
show alarm details
show log: all
show version
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the affected node', 'Action': 'Power off the node, wait for 10 seconds, and then power it back on.'}
- Step 2: {'Step': 'Check for hardware failure in the line card', 'Action': '"Run 'show tech support' and 'show alarm details' to identify the faulty component.'}"}
- Step 3: {'Step': 'Update the node software to the latest version', 'Action': '"Run 'install new software' and follow the on-screen instructions.'}"}
- Step 4: {'Step': 'Verify the configuration', 'Action': '"Run 'show running-config' to check for any incorrect settings.'}"}

Post-Check Verification

```
show alarm details
show log: all
```

```
show version
show running-config
```